U/Side Of Kneeler To Top Of Hood Moulding

U/Side Of Cill To U/Side Of Kneeler Block

3343

4308

Section B-B
1:10

Plain Kneeler Block On Existing Should This Be Retained As Described

New Stone Pier

Stonework Surrounding The New Arch To Be Made Good

Plaster To Be Made Good Once New Stonework Is In Place

Lead Flashing To Be Reinstated Over The Hood Moulding

External Elevation
1:10

Decorative Kneeler Block To Be Matched From Existing

New Stone Pier

Note:
All Window Openings Are Handed On This Gable End

Adjacent Stone Ashlar To Be Cut To Receive New Lead Flashing In Connection With Plumbosest, See Our Drawing MDL/SAM/REF1

External Elevation
1:10

Internal

External

Rebate Detail For Upper Mullions

Rebate Detail Around Lancets

Rebate Detail For Lower Mullions

Plan Section A-A
1:10

GENERAL NOTES

REV.	DESCRIPTION	DATE

COPYRIGHT AND OWNERSHIP OF THIS DRAWING IS VESTED IN THE COMPANY NAMED ON THE DRAWING, WHOSE PRIOR WRITTEN CONSENT IS REQUIRED FOR ITS USE, REPRODUCTION OR FOR PUBLICATION TO ANY THIRD PARTY. ALL RIGHTS IN THE DESIGNS, DRAWINGS AND MODELS AND OTHER COPYRIGHT CONVENTIONS ARE RESERVED TO THE COMPANY NAMED ON THIS DRAWING AND MAY BE PROTECTED BY COURT PROCEEDINGS FOR DAMAGES AND/OR INJUNCTIONS AND COSTS.

MASONRY DESIGN LIMITED

SPECIALISTS IN THE DESIGN OF MASONRY AND ARCHITECTURAL CERAMICS

SUITE 507, DAISYFIELD BUSINESS CENTRE, APPLEBY STREET, BLACKBURN, LANCS. BB1 3BL
TEL: 01254 55055/50544 FAX: 01254 55508 E-MAIL: MAIL@MASONRYDESIGN.CO.UK

PROJECT

St Albans Church, Macclesfield

TITLE

New Stonework To East Elevation
Tracery Window, External Elevation

SCALE	1:10	DATE	Nov 99
DRAWN	P Taylor	C.A.D. REF	Window

DRG. No.

MDL / SAM / 01